


Received 02-02-17



**County of Door
HIGHWAY DEPARTMENT**

1001 S. Duluth Avenue
Sturgeon Bay, WI 54235

John P. Kolodziej, PE
Highway Commissioner
(920) 746-2500
kolodziej@co.door.wi.us

Ms. Kristin DuFresne,
Department of Natural Resources
2984 Shawano Avenue
Green Bay, WI 54313-6727

January 30, 2017

Subject: Door County Highway Department Salt Storage Facility
WDNR BRRTS #02-15-554088

Dear Ms. DuFresne,

Enclosed are the latest water sampling results for the subject site. Samples were obtained from 10392 Northwoods Drive and 10397 STH 57. Samples were not taken at 10363 STH 57 because a new deep water well was installed at this site. The table below identifies the sodium and chloride levels found during all of our sampling years since 2009.


	2009 Chloride Levels mg/l	2013 Chloride Levels mg/l	2015 Chloride Levels mg/l	2016 Chloride Levels mg/l	2009 Sodium Levels mg/l	2013 Sodium Levels mg/l	2015 Sodium Levels mg/l	2016 Sodium Levels mg/l
10392 Northwoods Drive	997	570	637	526	606	412.2	374	311
10363 STH 57	393	339	15.5	NA	226	208.4	6.42	NA
10397 STH 57	704	Not Available	461	414	183	Not Available	487	278

Please be advised that in the fall of 2016 a new deep water well was installed at 10392 Northwoods Drive. Therefore, no further well tests will be conducted for this property. The County is paying for the costs of the new well installation.

The table represents a general decline in the chloride and sodium levels since the County installed new storage facilities, modified handling procedures, and installed storm water management facilities. The County intends to annually check these chemical levels in the water from the remaining shallow well.

Should you have any questions, please do not hesitate to contact my office.

Sincerely,


John P. Kolodziej, PE
Highway Commissioner